AERBIO LTD.

320 North Walnut Bloomington, IN 47404

Tel: 812.334.1540 Fax: 812.334.1285 Emergency: 800.424.9300 **SECTION 1: IDENTIFICATION**

Effective Date:

Product Name: Peroxidase, horseradish

Molecular Formula: CAS No.: N/A

SECTION 2: HAZARDOUS INGREDIENTS: Possible biohazard.

SECTION 3: PHYSICAL DATA

Odor: N/A

Appearance: Freeze-dried powder.

Melting point.: N/A Boiling point: N/A

Decomposition temperature: N/A pH (depends on quality): N/A Solubility in water: N/A Specific gravity (water = 1) N/A

Vapor density: N/A Vapor pressure: N/A

SECTION 4: FIRE AND EXPLOSION DATA

Flash point: N/A Flammable limit: N/A Flammability: N/A Extinguishing media: N/A

Fire fighting procedures: Extinguish by any means appropriate to the surrounding fire.

Unusual fire and explosions hazards: none

SECTION 5: REACTIVITY DATA

Stable N/A Unstable

Decomposition byproducts: N/A Incompatibilities/Condition to Avoid: none

Hazardous Polymerization: N/A

SECTION 6: HEALTH HAZARD DATA

Toxicity: N/A

Route of Entry: May be harmful by inhalation, ingestion, or skin absorption. May cause irritation.

Permissible Exposure limits: N/A

TWA: TLV:

SECTION 7: SPILLAGE AND DISPOSAL PROCEDURES

Spillage: Wear chemical safety goggles and heavy rubber gloves. If dry is spilled, sweep up, place in bag and hold for waste disposal. Avoid raising dust. Ventilate area after material pickup is complete. If liquid suspension is spilled, wipe up liquid with rags or towles and discard in the proper waste container. Wash spill site thoroughly after material pickup is complete.

Disposal: Dissolve or mix material with a combustible solvent and burn in chemical incinerator equipped with an afterburner and scrubber.

SECTION 8: FIRST AID PROCEDURES

Eve Contact: Flush eyes with copious amounts of water for at least 15 minutes.

Skin Contact: Wash skin with soap and copious amounts of water.

Inhalation: Move to fresh air. If not breathing, give artificial respiration. If breathing is difficult,

administer oxygen.

Ingestion: Contact a physician.

SECTION 9: HANDLING AND STORAGE INFORMATION: Store at the correct stability tenperature in a dry place(see CofA). Hygroscopic.

AERBIO LTD. 320 North Walnut Bloomington, IN 47404

Tel: 812.334.1540 Fax: 812.334.1285 Emergency: 800.424.9300

SECTION 10: SPECIAL PROTECTION INFORMATION:

Ventilation: Whatever means necessary to prevent excessive dust. Use NIOSH approved respirator if dust

becomes pervasive.

Skin Protection: Impermeable gloves. **Eye Protection:** Splash-proof safety goggles. **Respiratory Protection:** see above.

Other:

SECTION 11: TRANSPORT INFORMATION DOT Classification: not a regulated material.

SECTION 12: OTHER REGULATORY INFORMATION

Federal and State regulations: WHMIS (Canada): N/A DSCL (EEC): N/A HMIS (USA): N/A